


T.				U_f	I_f	$D_{(g^2, g1)}$	U_a	U_{g^2}	U_{g1}	I_a	I_{g^2}	S
				V	A	%	V	V	V	mA	mA	mA/V
K 1658	AEG; RFT	1	1	7	1,1	15 ÷ 30	440	220	-25	50	10	3,2
K 1668	AEG; RFT	1	1	7	1,1	17 ÷ 23	500	250	maximum	$P_a = 15 W$	$I_{g^2} = 2 W$	
K 1678	AEG; RFT	1	1	7	1,1	19 ÷ 21						



³⁾ vide *4